End-of-Sale and End-of-Life Announcement for the Cisco MDS 9513 Multilayer Director

EOL10532

Cisco announces the end-of-sale and end-of life dates for the Cisco MDS 9513 Multilayer Director. The last day to order the affected product(s) is October 31, 2016. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1.   End-of-Life Milestones and Dates for the Cisco MDS 9513 Multilayer Director

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 31, 2015
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 31, 2016
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 29, 2017
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	October 31, 2017
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	October 31, 2017
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 31, 2017
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	July 11, 2021
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2022

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Table 2.   Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
DS-13SLT-FAN-F	MDS 9513 front installed fan tray	DS-C9710-FAN	MDS 9710 FAN Tray	
DS-13SLT-FAN-F=	MDS 9513 front installed fan tray, Spare	DS-C9710-FAN=	MDS 9710 FAN Tray	
DS-13SLT-FAN-R	MDS 9513 rear installed fan tray	DS-C9710-FAN	MDS 9710 FAN Tray	
DS-13SLT-FAN-R=	MDS 9513 rear installed fan tray, Spare	DS-C9710-FAN=	MDS 9710 FAN Tray	
DS-9513-KIT-CCO	MDS 9513 Accessory Kit for CCO	DS-9710-KIT-CCO	MDS 9710 Accessory Kit for Cisco	
DS-9513-KIT-CCO=	MDS 9513 Accessory Kit for CCO, Spare	DS-9710-KIT-CCO=	MDS 9710 Accessory Kit for Cisco	
DS-9513-KIT-DM	MDS 9513 Accessory Kit for Demo	DS-9710-KIT-DM	MDS 9710 Accessory Kit for Demo	
DS-9513-KIT-EMC	MDS 9513 Accessory Kit for EMC	DS-9710-KIT-EMC	MDS 9710 Accessory Kit for EMC	
DS-9513-KIT-HDS	MDS 9513 Accessory Kit for HDS	DS-9710-KIT-HDS	MDS 9710 Accessory Kit for HDS	
DS-9513-KIT-HP	MDS 9513 Accessory Kit for HP	DS-9710-KIT-HP	MDS 9710 Accessory Kit for HP	
DS-9513-KIT-IBM	MDS 9513 Accessory Kit for IBM	DS-9710-KIT-IBM	MDS 9710 Accessory Kit for IBM	
DS-9513-KIT-NPE	MDS 9513 Accessory Kit for NPE	There is currently no replacement product available for this product.		
DS-9513-KIT-SUN	MDS 9513 Accessory Kit for SUN	There is currently no replacement product available for this product.		
DS-C9513	MDS 9513 Chassis	DS-C9710	MDS 9710 Chassis No Power Supplies, Fans Included	
DS-C9513-4AHK9	MDS 9513: Chassis, 2x(Sup2A, FAB3, 6K PS) for HP with Service	DS-C9710H-1K9	MDS 9710 Base Config HP Chassis FANs 2 Sup-1 3 Fab-1 6 PS 3K	
DS-C9513-4AK9	MDS 9513 Base Config: Chassis, 2 Sup-2A, 2 Fabric3, 2 6K PS	DS-C9710-1K9	MDS 9710 Base Config Chassis FANs 2 Sup-1 3 Fab-1 6 PS AC 3K	
DS-C9513-CL	MDS 9513 Clock Module	There is currently no replacement product available for this product.		
DS-C9513-CL=	MDS 9513 Clock Module, Spare	There is currently no replacement product available for this product.		
DS-C9513-IBM	MDS 9513 Base Config: Chassis, 2 Fabric, 2 6K AC PS	There is currently no replacement product available for this product.		
DS-C9513=	MDS 9513 Chassis, Spare	DS-C9710=	MDS 9710 Chassis, Spare No Power Supplies, Fans included	
DS-CAC-6000W	MDS 9513 6000W AC power supply	DS-CAC97-3KW	MDS 9700 3000W AC power supply	
DS-CAC-6000W=	MDS 9513 6000W AC power supply, Spare	DS-CAC97-3KW=	MDS 9700 3000W AC power supply	

Product Migration Options

Customers are encouraged to migrate to the Cisco MDS 9710 Multilayer Director. Information about this product can be found at:
http://www.cisco.com/c/en/us/products/storage-networking/mds-9710-multilayer-director/index.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at
http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco MDS 9513 Multilayer Director through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:
http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco MDS 9710 Multilayer Director, visit
http://www.cisco.com/c/en/us/products/storage-networking/mds-9710-multilayer-director/index.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to:
http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to:
http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

CISCO

Printed in USA   C51-735660-00   9/15