

End-of-Sale and End-of-Life Announcement for the Cisco MDS 9020 Series Fabric Switch

EOL5547

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco MDS 9020 Series Fabric Switch. The last day to order the Cisco MDS 9020 Series Fabric Switch is September 27, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco MDS 9020 Series Fabric Switch. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the Cisco MDS 9124 1/2/4-Gbps 24-Port Multilayer Fabric Switch. With its flexibility to expand from 8 to 24 ports in 8-port increments, the Cisco MDS 9124 offers the densities required for both departmental storage area network (SAN) switches and edge switches in enterprise SANs.

Table 1. End-of-Life Milestones and Dates for the Cisco MDS 9020 Series Fabric Switch

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 29, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 27, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 26, 2007
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	September 26, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	September 26, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	December 23, 2011
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 25, 2012

- HW = Hardware
- OS SW = Operating System Software
- App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
DS-C9020-20K9	MDS 9020 20-Port 4 Gbps Fibre Channel Fabric Switch	DS-C9124-K9	MDS 9124 24-port 4Gbps FC switch (8-port base config)

Product Migration Options

The recommended replacement for the Cisco MDS 1/2-Gbps 9020 Fabric Switch is the Cisco MDS 9124 1/2/4-Gbps 24-Port Multilayer Fabric Switch. The Cisco MDS 9124 is compatible with Cisco MDS 9500 Series multilayer directors and Cisco MDS 9200 Series multilayer fabric switches, providing transparent, end-to-end service delivery in core-edge deployments. Further information can be found at

http://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5987/ps7079/product_data_sheet0900aecd8057451f.html.

Table 3. Product Comparisons

Feature	Cisco MDS 9020 1/2-Gbps 20-Port Fabric Switch	Cisco MDS 9124 1/2/4-Gbps 24-Port Multilayer Fabric Switch
Max Interface Speed	4-Gbps	4-Gbps
Autosensing FC Interfaces	20 1/2/4-Gbps FC Ports	24 1/2/4-Gbps FC Ports
Dual Power Supply	No	Yes
On-Demand Port Activation	No	Yes
Operating System	FabricWare	SAN-OS
QuickConfig Wizard	No	Yes
Intelligent Network Services—Integrated Support for VSAN, ACLs, QOS	No	Yes
Comprehensive Security Services	No	Yes
Port Channels	No	Yes

Customers may purchase the Cisco MDS 9124 1/2/4-Gbps 24-Port Multilayer Fabric Switch from EMC Corporation, IBM Corporation, Hitachi Data Systems, Hewlett Packard, Xiotech, Sun, Network Appliance, Dell, NEC, Fujitsu all of whom are designated Original Storage Manufacturer (OSM) or Solutions Technology Integrator (STI) partners, or from any of these companies' resellers. Cisco does not offer trade-in credits or a trade-in program.

For More Information

For more information about the Cisco MDS 9124 24-Port Multilayer Fabric Switch, visit <http://www.cisco.com/en/US/products/ps7079/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Americas Headquarters
Cisco Systems, Inc.
170 West Taftman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 520-4000
800 653-1115 (toll free)
Fax: 408 527-0689

Asia Pacific Headquarters
Cisco Systems, Inc.
155 Robinson Road
#26-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Hertfordseweg 13-19
1101 CH Amsterdam
The Netherlands
www.europe.cisco.com
Tel: +31 0 20 620 0791
Fax: +31 0 20 657 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Ring logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access, Register, Attend, EPX, Catalyst, CDDA, CDDP, DCE, CCIP, CDNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Discovery/Solver, EtherChannel, EtherFast, EtherSwitch, Fax Step, Follow Me Browsing, FormShare, Gigaset, HomeLink, Internet Quotient, IQS, iPhone, IPTV, IQ Director, the IQ logo, IQ Net, Roadshow, Scorecard, iQuick Study, iShareStream, iLinkaya, iMeeting Place, iMGX, iNetworking Academy, iNetwork Register, iPacket, iPK, iProConnect, iRabitMUX, iScriptShare, iSiteCast, iSMARTnet, iStackWise, iThe Router, iWay to Increase Your Internet Quotient, and iWorkPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (07012)